



# **Technical Information Bulletin**

Date 3/24/2003

## **OD4300**

**Symptom – Lexan assembly will not attach to OD4000/OD4800 or OD3500 because the slots for the attaching knobs are too narrow.**

**Solution – Machine slots wider to allow knobs to fit.**

**Affected serial numbers 46446 – 46545.**

